


Simplified motor transfer function
(Without inductance, L_a):

$$\frac{\theta(s)}{V_a(s)} = \frac{k}{s \cdot (s + a)}$$

From the first lab you should have found the constants k and a to be approximately: $k := 940$ $a := 100$

Now this motor is part of a control loop:

The system block diagram



$$\begin{aligned} \text{Overall transfer function: } H(s) = \frac{\theta_{\text{out}}(s)}{\theta_{\text{in}}(s)} &= \frac{k_p \cdot \left[\frac{940}{s \cdot (s + 100)} \right]}{1 + k_p \cdot \left[\frac{940}{s \cdot (s + 100)} \right] \cdot 1} = \frac{k_p \cdot 940}{s \cdot (s + 100) + k_p \cdot 940} \\ &= \frac{k_p \cdot 940}{s^2 + 100 \cdot s + k_p \cdot 940} \end{aligned}$$

ECE 3510 DC Second-Order Lab, p2

For critical damping: $100^2 - 4 \cdot (k_p \cdot 940) = 0$

$$10000 = 3760 \cdot k_p \quad k_p := \frac{10000}{3760} \quad k_p = 2.66$$

Input step: $90 \cdot \text{deg} = 1.571 \cdot \text{rad}$ $X(s) = \frac{1.571}{s}$

Step response: $Y(s) = X(s) \cdot H(s) = \frac{1.571}{s} \cdot \frac{k_p \cdot 940}{s \cdot (s + 100) + k_p \cdot 940} = \frac{1.571}{s} \cdot \frac{2.66 \cdot 940}{s^2 + 100 \cdot s + 2.66 \cdot 940}$

$$= \frac{1.571 \cdot 2.66 \cdot 940}{s \cdot (s + 50)^2} = \frac{3928}{s \cdot (s + 50)^2} \quad H(0) = 1.571$$

$$= \frac{1.571}{s} + \frac{B}{(s + 50)} + \frac{C}{(s + 50)^2}$$

$$3928 = 1.571 \cdot (s + 50)^2 + B \cdot s \cdot (s + 50) + C \cdot s$$


let $s := -50$

$$3928 = 0 + 0 + C \cdot (-50) \quad C = \frac{3928}{-50} = -78.56$$

$$3928 = 1.571 \cdot s^2 + 157.1 \cdot s + 3928 + B \cdot s^2 + B \cdot 50 \cdot s - 75.56 \cdot s$$

$$B := -1.571$$

$$y(t) := 1.571 - 1.571 \cdot e^{-50 \cdot t} - \frac{3928}{50} \cdot t \cdot e^{-50 \cdot t}$$



ECE 3510 DC Second-Order Lab, p3

$$Y(s) = X(s) \cdot H(s) = \frac{1.571}{s} \cdot \frac{k_p \cdot 940}{s^2 + 100s + k_p \cdot 940}$$

For under damping: $s^2 + 100s + k_p \cdot 940 = (s + a)^2 + b^2 = s^2 + 2 \cdot a \cdot s + a^2 + b^2$
 $a := 50$

Choose imaginary part at twice the real part: $\frac{a}{b} = \frac{1}{2}$ in eq. 3.37, p.33 in text $b := 100$


$$a^2 + b^2 = 50^2 + 100^2 = 1.25 \cdot 10^4 = k_p \cdot 940$$

$$k_p := \frac{1.25 \cdot 10^4}{940} \quad k_p = 13.298$$

Input step: $90\text{-deg} = 1.571 \cdot \text{rad}$ $X(s) = \frac{1.571}{s}$

Step response: $Y(s) = X(s) \cdot H(s) = \frac{1.571}{s} \cdot \frac{13.3 \cdot 940}{(s + 50)^2 + 100^2}$ $x_m \cdot H(0) = \frac{1.571 \cdot 13.3 \cdot 940}{(0 + 50)^2 + 100^2} = 1.571$

$$y(t) := 1.571 - 1.571 \cdot e^{-50 \cdot t} \cdot \cos(100 \cdot t) - 1.571 \cdot \frac{50}{100} \cdot e^{-50 \cdot t} \cdot \sin(100 \cdot t) \quad \text{From eq. 3.37, p.33}$$



ECE 3510 DC Second-Order Lab, p4

Frequency Response Curves

$$k_p := 2.66 \quad M_1(\omega) := \left| \frac{10 \cdot k_p \cdot 940}{-\omega^2 + 100 \cdot j \cdot \omega + k_p \cdot 940} \right|$$


$$\text{Phase}_1(\omega) := \arg \left(\frac{k_p \cdot 940}{-\omega^2 + 100 \cdot j \cdot \omega + k_p \cdot 940} \right)$$

$$k_p := 13 \quad M_2(\omega) := \left| \frac{10 \cdot k_p \cdot 940}{-\omega^2 + 100 \cdot j \cdot \omega + k_p \cdot 940} \right|$$

$$\text{Phase}_2(\omega) := \arg \left(\frac{k_p \cdot 940}{-\omega^2 + 100 \cdot j \cdot \omega + k_p \cdot 940} \right)$$

(Note that I used 10 rather than 1.571 / 9 to get degrees)

Magnitude of the Transfer function



Phase of the Transfer function

