

ECE 3600 Exam 2 Information

You may write more on this sheet. You may also use Exam 1 Information

Synchronous Machines

for 60Hz systems $n_{sync} = \frac{7200 \cdot \text{rpm}}{\text{poles}}$ $\omega_{sync} = \frac{4 \cdot \pi \cdot f}{N_{poles}}$

When spinning, the induced armature voltages (E_A for our phase) depends on the field current, I_f . I_f cause the field flux (call **excitation**).

Pullout power is the maximum power a generator can produce for a given excitation, at $\delta=90^\circ$



$$P_{po} = \frac{E_A \cdot V_\phi \cdot \sin(90\text{-deg})}{X_s} = \frac{E_A \cdot V_\phi}{X_s}$$

Generators

Over-excited condition, GOOD, supplies +Q (+VARs).

Note: Voltages and currents are magnitudes, not complex numbers

The **signs** of the angles are **important!**




$$E_A = V_\phi + I_A \cdot j \cdot X_s$$


$$P_{1\phi} = \frac{V_\phi \cdot E_A \cdot \sin(\delta)}{X_s} = V_\phi \cdot I_A \cdot \cos(\theta) \quad \delta = \arcsin\left(\frac{P_{1\phi} \cdot X_s}{V_\phi \cdot E_A}\right)$$

$$Q_{1\phi} \text{ (produced)} = \frac{V_\phi \cdot E_A \cdot \cos(\delta) - V_\phi^2}{X_s} = V_\phi \cdot I_A \cdot \sin(-\theta)$$

Motors



$$V_\phi = E_A + I_A \cdot j \cdot X_s$$



Over-excited condition, GOOD, supplies +Q (+VARs). uses -Q

(θ is measure in opposite direction to a regular load)

Important relations


$$E_A \cdot \sin(|\delta|) = X_s \cdot I_A \cdot \cos(\theta)$$

$$P_{1\phi} = \frac{E_A \cdot V_\phi \cdot \sin(|\delta|)}{X_s} = V_\phi \cdot I_A \cdot \cos(\theta)$$

$$Q_{1\phi} \text{ (used)} = \frac{V_\phi^2 - E_A \cdot V_\phi \cdot \cos(\delta)}{X_s} \quad (\text{Bigger } E_A \text{ makes } Q \text{ negative (good)})$$

$$= V_\phi \cdot I_A \cdot \sin(-\theta) \quad E_A = V_\phi - I_A \cdot j \cdot X_s$$

Under-excited condition, BAD, absorbs (uses) +Q (+VARs). like an inductor



Induction Motors


Typical torque-speed and power-speed curves for a 4-pole Induction motor

$$n_{slip} = n_{sync} - n_m = s \cdot n_{sync}$$

$$slip \ s = \frac{n_{slip}}{n_{sync}} = \frac{n_{sync} - n_m}{n_{sync}}$$


$$n_m = \text{the mechanical speed of the rotor} \\ = (1 - s) \cdot n_{sync}$$

$$\omega = n \cdot \left(2 \cdot \pi \cdot \frac{\text{rad}}{\text{rev}} \right) \cdot \left(\frac{\text{min}}{60 \cdot \text{sec}} \right) \\ \frac{\text{rad}}{\text{sec}} \quad \text{rpm}$$



No slip so no induced voltage and current in the rotor and thus no torque

$$3 \cdot (I_1^2 \cdot R_1) = P_{SCL} = \text{Stator Copper Losses}$$



$$3 \cdot (I_2^2 \cdot R_2) = P_{RCL} = \text{Rotor Copper Losses}$$

$$3 \cdot \left[I_2^2 \cdot \frac{R_2}{s} \cdot (1-s) \right] = P_{conv} \\ = (1-s) \cdot P_{AG} \\ = \text{power converted to mechanical}$$


$$3 E_1^2 / R_C = P_{core} = \text{core loss}$$

$$P_{out} = P_{conv} - P_{mech} - P_{misc} \\ \text{mechanical losses}$$

$$\text{induced torque} = \tau_{ind} = \frac{P_{conv}}{\omega_m} \quad \text{OR:} \quad \tau_{ind} = \frac{P_{AG}}{\omega_{sync}} \quad (\text{N}\cdot\text{m})$$

$$\text{load torque} = \tau_{load} = \frac{P_{out}}{\omega_m}$$

Power Flow



Per Unit S_{base} is the same across the entire system.

V_{base} = The nominal V_L (V_{LL}) in each region of the power system, where regions are separated by transformers.

$$I_{base} = \frac{S_{base}}{\sqrt{3} \cdot V_{base}} \quad Z_{base} = \frac{V_{base}^2}{S_{base}} \quad \text{Base changes} \quad Z_{pu} = Z_{pu_device} \cdot \frac{S_{base} \cdot (V_{rated})^2}{S_{rated} \cdot (V_{base})^2}$$

Often the device: $V_{rated} = V_{base}$